

APPENDIX A

Location Maps

Written Directions to FCI Facilities

Directional Map to FCI Facilities

Production Test Facility (PTF) Chemical Storage Locations for Emergency Responders

Administrative Area Chemical Storage Locations

Directions to Florence Copper

From N AZ 79 (N Pinal Pkwy)

Turn West onto Hunt Highway

Travel approximately 2.1 miles

Turn Left into the Florence Copper Main Gate

Check in with Security, then proceed

At the stop sign:

Turn Left for the Administrative Building

Turn Right for the Production Test Facility and Wellfield

I 10 from the south

Take Exit 211 toward AZ-87 N/Coolidge/Florence

Merge onto Eisenhower St (0.58 mi)

Eisenhower becomes State Hwy 87/AZ – 87/AZ-84 (0.27 mi)

Take S State Rte 87/AZ-87 toward Coolidge/Florence (18.73 mi)

Turn Rt. Onto E. Hwy 287/AZ-287 (3.04 mi.)

Turn Lt. onto N. Attaway Rd. (3.01 mi)

Turn Rt. Onto Hunt Hwy (3.26 mi)

Florence Copper Inc., 1575 W. Hunt Hwy is on the Right

Check in with Security, then proceed

At the stop sign:

Turn Left for the Administrative Building

Turn Right for the Production Test Facility and Wellfield

I-10 from the north

Take Exit 185 AZ-187/AZ-387 toward Coolidge/Florence (0.33 mi)

Keep Left to take ramp toward Coolidge/Florence (0.3 mi)

Turn Left onto N Pinal Ave/AZ-387/AZ-187 (0.40 mi)

Turn Rt onto State Hwy 387/AZ-387 (6.92 mi)

Turn Rt onto State Hwy 87/AZ-87 (7.00 mi)

Stay straight onto E Hwy 287/AZ-287 (2.95 mi)

Turn Lt. onto N. Attaway Rd. (3.01 mi)

Turn Rt. Onto Hunt Hwy (3.26 mi)

Florence Copper Inc., 1575 W. Hunt Hwy is on the Right.

Check in with Security, then proceed

At the stop sign:

Turn Left for the Administrative Building

Turn Right for the Production Test Facility and Wellfield




Figure 1. Florence Copper, Inc. Location




Figure 2. Florence Copper, Inc. General Site Map




Figure 3. PTF Facility




Figure 3. Administrative Area